ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0277, W0216	NA	Near Lakshmi Temple
Segment No.	**Total Length (m)**	
12/C-W0277/S033529	123.98	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	123.98	77.514392	13.074405	77.514852	13.075431	W0277	W0277

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads Abbigere circle to Lakshmi temple and surrounding area (Piple line road) in ward no 12 Shettyhalli	9900000	2020
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Others	
Tender	**Work Details**	**Job No. / Work Code**
Tender		012-20-000117
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/79/2021-22	05/01/2022	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
26/04/2022	26/04/2022	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B J Kumar		10361589.00
Phone No.	**E-Mail ID**	
9845937211		

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರ
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು

Field Inspection Details

Number of Trees

0

Any Other Information

Name

Krishnamurthy

Date of Inspection

27/04/2022

Remarks

Category	Image	Photo Remark
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	30/04/2022	27/05/2022	APPROVED
EE	EE DAS	30/04/2022	27/05/2022	Completed
AEE	Janardhan	27/04/2022	27/05/2022	Forwarded
AE	Krishnamurthy SN	27/04/2022	27/05/2022	Fowarded
AE	Krishnamurthy SN	27/04/2022	27/05/2022	Created